

MK 500 INSTALLATION INSTRUCTIONS

CAUTION


- **1.** Locate and identify all parts using hardware lists and the drawings.
- 2. Heaving items should be hoisted up to the work area using appropriate machinery, ie. hoisting lifts, block and tackle, etc.
- 3. Make sure MK 500 Beam Mounting Kit and motors/spools are securely attached, and all bolts are properly tightened before testing operation.
- 4. Keep area below cleared of people during installation, testing and initial operation.





Bolt together using 4 pcs %" bolts, flat washers, lock washers and nuts.

Note how this end overhangs, when viewed from rope window side. (This centers the rope drum under the beam that the unit is mounted to.)



USA: Tork Winch USA LLC 5020 Hazel Jones Road Bossier City, LA | 71111

9³/₁₆

CANADA: Torkwinch 125 Bysham Park Drive Woodstock, ON | N4T 1P1 P: 1-866-829-4411 E: sales@torkwinch.com F: 1-519-539-9191

